

NY Thermal Inc.
Tel: (506) 657-6000
Toll Free: 1-800-688-2575
Fax: 1-506-432-1135
Web: www.nythermal.com
Email: info@nythermal.com

84915 Diverter Valve Stepper Motor (59200138)

Applicable Boiler Models

- Tx151C, Tx200C, VM110P,

Kit Contents

- 1 Diverter Valve Stepper Motor (see Figure 1)

Tools Required

- ¼" Nut Driver

Replacement Instructions

- 1) Turn off power and gas to the boiler.
- 2) Remove front cover.
- 3) Disconnect wires from the diverter motor.
- 4) Unclip the motor by pulling up on it and replace.
- 5) Reconnect wires.
- 6) Replace front cover.




Figure 1

NOTICE

Power Off - Failure to turn off the power before servicing this part may cause misalignment that could damage the boiler.




Figure 2