

NY Thermal Inc.
Tel: (506) 657-6000
Toll Free: 1-800-688-2575
Fax: 1-506-432-1135
Web: www.nythermal.com
Email: info@nythermal.com

84993

M5 Reset Safety Switch

Applicable Boiler Models

Lx300-800

Kit Contents:

- M5 Reset Safety Switch

Tools Required

- 5/8" wrench

Replacement Instructions

- 1) Open burner door to Combustion Chamber.
- 2) Inspect Combustion Chamber for any scorching or damage.
- 3) If there is damage contact NTI immediately.
- 4) If there is no damage install new Safety Switch where the old one is located.
- 5) Test boiler for proper operation.



⚠ WARNING

Replacing a Reset Safety Switch without diagnosing and correcting the cause of the failure will result in overheating leading to fire, serious injury, or death.