

NTI Boilers Inc.  
Tel: (506) 657-6000  
Toll Free: 1-800-688-2575  
Fax: 1-506-432-1135  
Web: www.ntiboilers.com  
Email: info@ntiboilers.com

## 84387-1 Flue Outlet Adapter with Tabs



This boiler must be serviced by a qualified heating technician. Failure to properly maintain or service this appliance may result in property damage, serious injury to occupants or, death.

### Applicable Boiler Models

- Lx300 – 600
- Ti400

### Kit Contents


- 1 Flue outlet adapter

### Tools Required

- 3/8 Nut Driver or Flat Head screwdriver
- Tin snips

### Replacement Instructions

- 1) For Lx500 or Lx600 this is a direct fit replacement.
- 2) On a Ti400 cut the four down tabs flush with the adapter as shown.
- 3) On Lx300-400 boilers not originally equipped with tabs, cut the tabs flush with the adapter as shown
- 4) Check the flue connection for leaks.



For Ti400 **ONLY**, Cut Tabs, flush with adapter  
\*\*Lx300-400 Boilers: Only remove tabs if the original boiler was not equipped with tabs.

**\*\*Some Lx300-400 boilers are equipped with tabs from the factory. If your ILx300-400 boiler was originally equipped with tabs do not cut the tabs this is a direct fit replacement.**

**Flue Adapter Installation** – The Flue adapter and test grommet prevent flue gas from escaping. Failure to properly install the adapter or grommet will result in flue gas leakage leading to serious injury or death.

