

**NY Thermal Inc.**  
Tel: (506) 657-6000  
Toll Free: 1-800-688-2575  
Fax: 1-506-432-1135  
Web: www.nythermal.com  
Email: info@nythermal.com

## 84781-1 Outlet Sensor, clip-on Tasseron

### **⚠ WARNING**

This boiler must be serviced by a qualified heating technician. Failure to properly maintain or service this appliance may result in property damage, serious injury to occupants or, death.

### Applicable Boiler Models

- Tx51
- Tx81
- Tx101
- Tx151
- Tx200
- Tx151C
- Tx200C

### Kit Contents

- 1 Tasseron Outlet Sensor
- 1 Smaller Clip

### Tools Required

- ¼" Nut Driver
- Needle nose pliers

### Replacement Instructions

- 1) Turn off power and gas to the boiler.
- 2) Unclip the old sensor and remove it.
- 3) Place the new sensor on the outlet pipe and secure with the retaining clip.



For boilers Serial number 72000 and lower, replace the metal locking clip with the smaller one that is included in the kit.

- 4) Power up the boiler and check for proper operation

### **⚠ DANGER**

**Outlet sensor location-** Failure to properly secure the outlet sensor will result in the boiler overheating, which may lead to serious injury or death.

### **⚠ WARNING**

The installation of this kit must be performed by a qualified boiler technician. Installing this kit without the proper background and training is hazardous and may result in property damage or death.